
Bierprotector mit CO_2-Automatic

Hält angestochene Partyfässer frisch



TEILE

1. Bierprotector
2. Rändelschraube
3. Kapselhalter
4. Aufsteckkonus
5. Flügelschraube

Wozu


Der Bierprotector verhindert, dass das Bier schal wird, wenn längere Zeit nicht gezapft wird – zum Beispiel über Nacht (dann das Fass möglichst in den Kühlschrank stellen). Steht das Bier unter Druck, kann die Kohlensäure nicht entweichen.

Anwendung

1. Bierprotector (1) bis zum Anschlag in den Stopfen des bereits angestochenen Partyfasses stecken.
2. CO_2-Automatic auf Null stellen: Rändelschraube (2) gegen den Uhrzeigersinn bis zum Anschlag drehen.
3. Kapselhalter (3) abschrauben, eine 16-g-CO_2-Kapsel einlegen und den Kapselhalter fest anschrauben. Ein kurzes Zischen zeigt, dass sie bereit ist.
4. CO_2-Automatic mit dem Aufsteckkonus (4) auf den Bierprotector (1) stecken.
5. Rändelschraube (2) im Uhrzeigersinn drehen, bis der gewünschte Druck eingestellt ist (meist 3 bis 4 Umdrehungen). Beim höchsten Druck von ca. 1,3 bar ist ein Klicken zu hören.
6. Ist das Fass leer: Rändelschraube auf Null zurückdrehen, CO_2-Automatic abnehmen, Flügelschraube (5) am Bierprotector öffnen und alles aus dem Stopfen ziehen.

Beer Protector with CO_2 Automatic

Keeps tapped party kegs fresh



PARTS

1. Beer Protector
2. Knurled screw
3. Capsule holder
4. Slip-on cone
5. Wing screw

Purpose

The Beer Protector stops beer from going flat when tapping is interrupted for a longer time – for example overnight (put the keg in the refrigerator if possible). Under pressure, the carbon dioxide cannot escape from the beer.

Use

1. Push the Beer Protector 1 as far as it will go into the bung of the party keg that has already been tapped.
2. Set the CO_2 Automatic to zero: turn the knurled screw 2 anticlockwise as far as it will go.
3. Unscrew the capsule holder 3, insert a 16 g CO_2 capsule and screw the holder on firmly. A short hiss shows that it is ready.
4. Push the CO_2 Automatic with its slip-on cone 4 onto the Beer Protector 1.
5. Turn the knurled screw 2 clockwise until the required pressure is set (usually 3 to 4 turns). At the maximum pressure of approx. 1.3 bar you will hear a click.
6. When the keg is empty: turn the knurled screw back to zero, remove the CO_2 Automatic, open the wing screw 5 on the Beer Protector and pull everything out of the bung.